


Our property at 1122 S 8th that received a self initiated inspection from Schwartz





1132 S 8th. Two doors to the north.
Many violations, but no SI inspection





If one house on the block warrants a self initiated inspection it would be this one at 1111 S 8th. The failed roof, falling gutters paint etc did not catch Schwartz's attention



1123 S 8th - needs more painting, siding etc than ours





1123 S 8th - needs more painting, siding etc than ours

